


LUXOR H.WILSON

Presentation Station Instructions

Parts List








Tools Included

- Allen Wrench



L x4










2 M6*28 x4




3 M6*10 x20






2



3



4

